


Lockout/Tagout — The 6 Steps Before Service or Maintenance

Lockout/Tagout (LOTO) controls hazardous energy during servicing and maintenance of machinery. Skip a step and you create the conditions for the unexpected energization that kills roughly 120 workers and seriously injures 50,000 each year.



Need a written LOTO program, machine-specific procedures, or annual authorized-employee training and audits?

bluehive.com · 260-217-5328 ·
support@bluehive.com